


**UNCLASSIFIED**

NATIONAL DAM SAFETY PROGRAM. HIGHLAND LAKE DAM (NJ00240), PASSA--ETC(U)  
AUG 78 R GERSHOWITZ

DACW61-78-C-0124

NL

AD  
A0600 7



MICROCOPY RESOLUTION TEST CHART  
NATIONAL BUREAU OF STANDARDS-1963-A

AD A060017

Approved for public release;  
distribution unlimited

①  
**LEVEL III**

PASSAIC RIVER BASIN

SLIPPERY ROCK BROOK, PASSAIC COUNTY


NEW JERSEY

*See back  
page for 1473*  
**HIGHLAND LAKE DAM**

**PHASE I INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM**

DDC FILE COPY

NJ 00240



**DEPARTMENT OF THE ARMY  
PHILADELPHIA DISTRICT, CORPS OF ENGINEERS  
CUSTOM HOUSE - 2D & CHESTNUT STREETS  
PHILADELPHIA, PENNSYLVANIA 19106  
AUGUST 1978**

8 10 10 078

NOTICE

THIS DOCUMENT HAS BEEN REPRODUCED  
FROM THE BEST COPY FURNISHED US BY  
THE SPONSORING AGENCY. ALTHOUGH IT  
IS RECOGNIZED THAT CERTAIN PORTIONS  
ARE ILLEGIBLE, IT IS BEING RELEASED  
IN THE INTEREST OF MAKING AVAILABLE  
AS MUCH INFORMATION AS POSSIBLE.

8 10 10 078





IN REPLY REFER TO

NAPEN-D

DEPARTMENT OF THE ARMY  
PHILADELPHIA DISTRICT, CORPS OF ENGINEERS  
CUSTOM HOUSE-2 D & CHESTNUT STREETS  
PHILADELPHIA, PENNSYLVANIA 19106

Honorable Brendan T. Byrne  
Governor of New Jersey  
Trenton, New Jersey 08621

26 SEP 1978

ACCESSION for	
NTIS	White Section <input checked="" type="checkbox"/>
DDC	Buff Section <input type="checkbox"/>
UNANNOUNCED	<input type="checkbox"/>
JUSTIFICATION	EX. NP
BY	
DISTRIBUTION/AVAILABILITY CODES	
Dist.	AVAIL. and/or SPECIAL
A	

Dear Governor Byrne:

Inclosed is the Phase I Inspection Report for Highland Lake Dam in Passaic County, New Jersey which has been prepared under authorization of the Dam Inspection Act, Public Law 92-367. A brief assessment of the dam's condition is given in the front of the report.

Based on visual inspection, available records, calculations and past operational performance, Highland Lake Dam, initially listed as a high hazard potential structure but reduced to a significant hazard potential structure, as a result of this inspection, is judged to be in poor overall condition. The spillway is considered inadequate since 37 percent of the Probable Maximum Flood (PMF) would overtop the dam. To insure adequacy of the structure, the following actions, as a minimum are recommended:

a. The adequacy of the spillway should be determined by a qualified professional consultant, engaged by the owner, using more sophisticated methods, procedures and studies within six months from the date of approval of this report. Any remedial measures necessary to insure the adequacy of the spillway and to prevent overtopping should be initiated within calendar year 1979.

b. Within six months from the date of approval of this report, engineering studies and analyses should be performed to determine the composition and structural stability of the dam. Any remedial measures found necessary should be initiated within calendar year 1979. Engineering studies and analyses should also be performed to evaluate the capability of the large downstream parking lot to act as a dam and reduce downstream damages and loss of life in the event of failure of the Highland Lake Dam.

NAPEN-D

Honorable Brendan T. Byrne

c. The following actions should be taken within the indicated time from the date of approval of this report.

(1) Within three months the valve box should be cleared of all debris and the low level outlet and the gate valve should be repaired or replaced.

(2) Within six months a program for regularly observing seepage should be implemented.

(3) Within one year a drain should be provided through the wall of the valve box and the deteriorated facing of the drain should be repaired.


A copy of the report is being furnished to Mr. Dirk C. Hofman, New Jersey Department of Environmental Protection, the designated State Office contact for this program. Within five days of the date of this letter, a copy will also be sent to Congressman Joseph Minish of the Eleventh District. Under the provisions of the Freedom of Information Act, the inspection report will be subject to release by this office, upon request five days after the date of this letter.

Additional copies of this report may be obtained from the National Technical Information Services (NTIS), Springfield, Virginia, 22161 at a reasonable cost. Please allow four to six weeks from the date of this letter for NTIS to have copies of the report available.

An important aspect of the Dam Safety Program will be the implementation of the recommendations made as a result of the inspection. We accordingly request that we be advised of proposed actions taken by the State to implement our recommendations.

Sincerely yours,

1 Incl  
As stated



JOEL T. CALLAHAN

Lieutenant Colonel, Corps of Engineers  
Acting District Engineer

Cy furn:

Mr. Dirk C. Hofman, P.E., Deputy Director  
Division of Water Resources  
N. J. Dept. of Environmental Protection  
P.O. Box 2809  
Trenton, NJ 08625

HIGHLAND LAKE DAM (NJ00240)

CORPS OF ENGINEERS ASSESSMENT OF GENERAL CONDITIONS

This dam was inspected on 29 June and 6 July 1978 by Harris-ECI under contract to the State of New Jersey. The state, under agreement with the U.S. Army Engineer District, Philadelphia, had this inspection performed in accordance with the National Dam Inspection Act, Public Law 92-367.

The Highland Lake Dam, initially listed as a high hazard potential structure but reduced to a significant hazard potential structure, as a result of this inspection, is judged to be in poor overall condition. The spillway is considered inadequate since 37 percent of the Probable Maximum Flood (PMF) would overtop the dam. To insure adequacy of the structure, the following actions, as a minimum are recommended:

a. The adequacy of the spillway should be determined by a qualified professional consultant, engaged by the owner, using more sophisticated methods, procedures and studies within six months from the date of approval of this report. Any remedial measures necessary to insure the adequacy of the spillway and to prevent overtopping should be initiated within calendar year 1979.

b. Within six months from the date of approval of this report, engineering studies and analyses should be performed to determine the composition and structural stability of the dam. Any remedial measures found necessary should be initiated within calendar year 1979. Engineering studies and analyses should also be performed to evaluate the capability of the large downstream parking lot to act as a dam and reduce downstream damages and loss of life in the event of failure of the Highland Lake Dam.

c. The following actions should be taken within the indicated time from the date of approval of this report.

(1) Within three months the valve box should be cleared of all debris and the low level outlet and the gate valve should be repaired or replaced.

(2) Within six months a program for regularly observing seepage should be implemented.

(3) Within one year a drain should be provided through the wall of the valve box and the deteriorated facing of the drain should be repaired.

APPROVED: Joel T. Callahan  
JOEL T. CALLAHAN  
Lieutenant Colonel, Corps of Engineers  
Acting District Engineer

DATE: 26 September 1978



1

PHASE I INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM

Name of Dam: Highland Lake Dam, I.D. NJ00240  
State Located: New Jersey  
County Located: Passaic  
Stream: Slippery Rock Brook  
Date of Inspection: June 29, and July 6, 1978

Assessment of General Condition

Highland Lake Dam is in poor condition with serious loosening of brick facing and spalling of gunite facing at the right abutment contact, and considerable leakage from drainholes in the gunite. The low level outlet is abandoned and the valve buried by gravel in the valve vault at the toe of the dam. However, a massive earthfill constructed in the early 1970's to provide a parking lot for the Bank of New Jersey office building provides substantial protection against loss of life and extensive property damage.

Highland Lake Dam does not have an adequate spillway capacity to pass the PMF, or even one-half of the PMF without overtopping. The dam's present spillway capacity can pass only about 36 percent of the PMF.

At present the engineering data available is not sufficient to make a definitive statement on the stability of the structure.

Nevertheless, even though the spillway capacity is inadequate and it is not possible, with the information which was available, to adequately assess the structural integrity of the dam, it is felt that the parking lot retaining wall and associated earthfill, which is subsequently discussed in this report, provides a substantial check against loss of life and excessive property damage by catastrophic failure of the dam.


The following remedial actions, however, are suggested along with a timetable for their completion.

1. The valve box should be cleared of all debris. The low level outlet and the gate valve itself should be repaired or replaced within 3 months, to ensure a reliable operational drawdown facility.
2. A program for regularly observing seepage should be implemented within six six months.

Furthermore, while of a less urgent nature, the following additional action is recommended and should be carried out within a reasonable period of time.

1. Any water entering the valve box, through stem leakage or through the dam itself, should be allowed to drain through a separate line leading out of the valve box. Therefore, a drain should be provided through the wall of the valve box.

Robert Gershowitz, P.E.







HIGHLAND LAKE

Dam and main spillway; service spillway is on right abutment at far shoreline.

June 29, 1978

## TABLE OF CONTENTS

### ASSESSMENT OF GENERAL CONDITION

		<u>Page</u>
SECTION 1	PROJECT INFORMATION . . . . .	1
	1.1 General . . . . .	1
	1.2 Description of Project . . . . .	2
	1.3 Pertinent Data . . . . .	5
SECTION 2	ENGINEERING DATA . . . . .	9
	2.1 Design . . . . .	9
	2.2 Construction . . . . .	9
	2.3 Operation . . . . .	9
	2.4 Evaluation . . . . .	10
SECTION 3	VISUAL INSPECTION . . . . .	11
	3.1 Findings . . . . .	11
	3.2 Evaluation . . . . .	13
SECTION 4	OPERATION PROCEEDURES . . . . .	14
	4.1 Procedures . . . . .	14
	4.2 Maintenance of Dam . . . . .	14
	4.3 Maintenance of Operating Facilities . . . . .	14
	4.4 Evaluation . . . . .	15
SECTION 5	HYDRAULIC/HYDROLOGIC . . . . .	16
	5.1 Evaluation of Features . . . . .	16
SECTION 6	STRUCTURAL STABILITY . . . . .	19
	6.1 Evaluation of Structural Stability . . . . .	19

## TABLE OF CONTENTS

(Continued)

	<u>Page</u>
SECTION 7      ASSESSMENT/REMEDIAL MEASURES . . . . .	21
7.1    Dam Assessment . . . . .	21
7.2    Remedial Measures . . . . .	23
7.3    Recommendations . . . . .	24

## PLATES

	<u>No.</u>
VICINITY MAP . . . . .	1
GEOLOGIC MAP . . . . .	2
DAM DRAWINGS . . . . .	3-5

## APPENDICES

APPENDIX A	-	CHECK LIST - VISUAL OBSERVATIONS CHECK LIST - ENGINEERING, CONSTRUCTION MAINTENANCE DATA
APPENDIX B	-	PHOTOGRAPHS
APPENDIX C	-	SUMMARY OF ENGINEERING DATA
APPENDIX D	-	HYDROLOGIC COMPUTATIONS

PHASE I INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM

HIGHLAND LAKE DAM, ID. NJ00240

SECTION 1: PROJECT INFORMATION

1.1 General

a. Authority

The National Dam Inspection Act (Public Law 92-367, 1972) provides for the National Inventory and Inspection Program by the U.S. Army Corps of Engineers. This inspection was made in accordance with this authority under contract C-FPM No. 35 with the State of New Jersey who, in turn, is contracted to the Philadelphia District of the Corps of Engineers.

b. Purpose of Inspection

The visual inspection of the Highland Lake Dam was made on June 29, and July 6, 1978. The purpose of the inspection was to make a general assessment as to the structural integrity and operational adequacy of the dam and its appurtenant structures.

c. Scope of Report

This report summarizes available pertinent data relating to the project; presents a summary of visual observations made during the Field Inspection; presents an evaluation of hydrologic and hydraulic conditions at the site; presents an evaluation as to the structural adequacy of the various project features; and assesses the general condition of the dam with respect to safety.

1.2 Description of Project

a. Description of Dam and Appurtenances

The original Highland Lake Dam, which remains in large part, is believed to be a stone masonry dam with brick facing. At a point some time ago, the brick facing was covered over with a coating of gunite varying in thickness from about 1-1/2 inches to more than 8 inches. The dam has a curved axis of about 104 feet long and a maximum height of 40 feet. The crest of the dam is covered with a concrete cap slab five feet wide.

The abutments are massive basalt rock on nearly vertical slopes. The dam is believed to be founded on the same basalt rock.

A concrete wing wall on the left abutment is backfilled with earth on the downstream side. The concrete wing wall is a concrete gravity structure with 2'-0" wide top and varies in height from zero to 10'-9" high. A similar concrete gravity wing wall extends from the service spillway on the right abutment.



The emergency spillway is a crest weir overshoot type located just right of the center of the dam. The chute slab is 26 feet wide and projects 5 feet from the downstream edge of the crest. The service spillway is a flat slab 18 feet wide and 22 feet long on the right abutment. The flows from the service spillway are discharged onto and flows as a waterfall down the right abutment rock. Both spillways are unregulated.

The low level outlet works is a 12-inch cast iron pipe through the base of the dam and just to the left of the center. A gate valve in a concrete valve vault at the base of the dam controls the outlet discharge.

b. Location

Highland Lake Dam is located in Passaic County, New Jersey. It is accessible by way of Highway 80 and either Squirrelwood Road or New Street. The parking lot for the Bank of New Jersey is located immediately downstream of the dam.

c. Size and Hazard Classification

Highland Lake Dam is classified in the dam size category as being "Intermediate", since its storage is less than 1,000 acre-feet, but its height is 40 feet. Since failure of the dam could cause loss of life and extensive property damage, a hazard potential classification of "Significant" has been assigned to the project. The dam was initially rated "High" hazard, but was downgraded after the field inspection, due to the presence of the fill downstream of the dam used to construct the parking lot.



d. Ownership

Highland Lake Dam is owned by the Bank of New Jersey, N.A., Post Office Box 2177, Patterson, New Jersey.

e. Purpose of Dam

The single present purpose of Highland Lake Dam is to retain the lake for aesthetic landscape around the Bank of New Jersey building.

f. Design and Construction History

No drawings or computations pertaining to the original construction could be found. No data from soil borings, soil tests, or other geotechnical data is available. The 1945 Plan of Repairs to Highland Lake Dam indicates that the original structure was constructed of stone masonry with earth backfill. A brick facing was constructed over the stone masonry. No cross sections of the original dam were available.

The Highland Lake Dam was damaged by a flood wave due to failure of Barbour's Pond dike in July 25, 1945 floods. The repairs and modifications to the dam included extending the spillway, new wing walls at both ends of the spillway, guniting both faces of dam, and protection of downstream toe of the dam.

Construction of the parking lot for the New Jersey Bank building has effectively created a second dam a few feet downstream of the Highland Lake Dam. The parking lot is nearly as high as Highland Lake Dam and was constructed by

building a high reinforced concrete retaining wall about 25 to 30 feet downstream of, and about parallel to, the dam and filling the gorge downstream of the retaining wall with earth. The space between the dam and the retaining wall was left unfilled leaving the dam exposed to view.

The spillways discharge into the void between the dam and parking lot. A six foot diameter concrete pipe culvert through the base of the retaining wall carries the spillway discharges under the parking lot. A concrete lined channel connects between the parking lot culvert and a similar culvert under Highway 80.

g. Normal Operational Procedures

The normal discharge from the lake is over the unregulated spillway and is allowed to naturally balance discharge with inflow to the lake. Due to the wide spillway, the normal depth of discharge is very shallow keeping the water level in the lake very stable. Since the low level outlet valve is inaccessible, it is not presently possible to lower the lake level below the spillway crest.

1.3 Pertinent Data

a. Drainage Area - 0.76 square miles

b. Discharge at Damsite

Maximum known flood at damsite	N.A.
Warm water outlet at pool elevation	N.A.
Diversion tunnel low pool outlet at pool elevation	N.A.

Diversion tunnel outlet at pool elevation	N.A.
Gated spillway capacity at pool elevation	N.A.
Gated spillway capacity at maximum pool elevation	N.A.
Ungated spillway capacity at maximum pool elevation	1,400 cfs (El. 237.82)
Total spillway capacity at maximum pool elevation	1,400 cfs

c. Elevation (Feet above MSL)

Top of dam (Top of East Wingwall)	237.82
Maximum pool-design surcharge	237.82
Full flood control pool	N.A.
Recreation pool	235.22
Spillway crest (both spillways)	235.22
Upstream portal invert diversion tunnel	N.A.
Downstream portal invert diversion tunnel	N.A.
Streambed at centerline of dam	215 feet (Estimated)
Maximum tailwater	N.A.

d. Reservoir

Length of maximum pool	1,000 $\pm$ feet (Estimated)
Length of recreation pool	920 $\pm$ feet (Estimated)
Length of flood control pool	N.A.

Design surcharge	64.5 acre-feet (El. 237.82)
Top of dam	64.5 acre-feet (El. 237.82)

f. Reservoir Surface (Acres)

Top of dam	6 $\pm$ acres (El. 237.82)
Maximum pool	6 $\pm$ acres (El. 237.82)
Flood control pool	N.A.
Recreation pool	5.7 $\pm$ acres (El. 235.22)
Spillway crest	5.7 $\pm$ acres (El. 235.22)

g. Dam

Type	Stone Masonry
Length	104 feet
Height	40 feet
Top width	5 feet
Side slopes	N.A.
Zoning	N.A.
Impervious core	N.A.
Cutoff	N.A.
Grout curtain	N.A.

h. Diversion and Regulating Tunnel (N.A.)

i. Spillways (Service and Emergency)

Types	Overflow
-------	----------

(Combined length of weir)	44 feet (Length of lowest portion)
Crest elevations	235.22
Gates	N.A.
Upstream channel	Reservoir
Downstream channel	6 foot diameter culvert

j. Regulating Outlets

12-inch cast iron pipe (inoperable)



## SECTION 2: ENGINEERING DATA

### 2.1 Design

No drawings or computations pertaining to original construction could be found. No data from soil borings, soil tests or other geological data is available. Drawings showing modifications to the dam were obtained from the New Jersey Department of Environmental Protection and are included in this report.

### 2.2 Construction

No records have been found as to the construction history of the dam. The owner's representative has no knowledge of, and does not know anyone having knowledge of, the construction history of the dam.

### 2.3 Operation

No records of operation of the lake are kept by the owner. The impoundment is allowed to operate naturally without regulation.



## 2.4

### Evaluation

#### a. Availability

The availability of engineering data is very poor. The only data available are the drawings pertaining to modifications to the dam and spillway, which can be obtained from the New Jersey Department of Environmental Protection.

#### b. Adequacy

The available engineering data is not sufficient to perform a comprehensive, definitive stability analysis of the structure. Data needed to fully assess the stability of the dam includes:

1. Subsurface information at the damsite, including engineering properties and parameters.
2. Cross sections of the structure.
3. Engineering properties of the masonry wall and earthfill.

A check list of engineering construction and maintenance is included in Appendix A.

### SECTION 3: VISUAL INSPECTION

#### 3.1 Findings

##### a. General

At the time of inspection the dam did not reveal any signs of distress. The inspection revealed that the structure is in a serviceable condition, but a regular program of inspection and repair is required to maintain its serviceability.

##### b. Dam

The face of the dam consisted of 2 to 6 inches of gunite with a grid of 1 inch diameter weep holes, many of which were discharging small quantities of clean water. It was determined, from an area where the gunite had broken away, that the original face of the dam was brick. The brick in this location, about four tenths of the height of the dam from the base at the right abutment, had become very loose at its contact with the abutment. A void, about 10 inches deep, has developed behind the gunite in this area. Considerable spalling of the gunite has occurred, particularly near the right abutment.

The right and left abutments are basalt and outcrops are frequently encountered along the rim of the impoundment. It is believed that the dam is founded on rock.

A prominent joint set exposed in the left abutment area strikes N5°E, and dips 80°SE and has a joint spacing of 1 to 3 feet. This joint set parallels a fault, mapped by others, about one-half mile east of the dam. Near the base of the dam, downstream of the left abutment, this prominent joint set is opened a maximum of 4 inches and average about 1-1/2 inches along a joint trace of 25 feet. (This feature is believed to be due to stress relief.) The rock in this area is broken by two additional joint sets mutually perpendicular, irregularly spaced (average-3 feet) and having variable trace lengths (average-less than 1 foot).

c. Appurtenant Structures

At the time of this inspection, the gate valve box was flooded and a slight flow out of the manhole cover was observed. The source of leakage could not be determined. In addition, the manhole cover was broken in a number of pieces and the valve box was partially filled with broken stone and other miscellaneous pieces of debris. This debris was piled up to within one foot of the manhole and completely covered the valve. At present the valve is not accessible and cannot be relied on to operate properly.

The concrete wing wall structures are in excellent condition. No settlement, tilting or misalignment were evident, and no structural cracks or spalling of concrete in the walls were found.

The spillways are serviceable, moderately rough and exhibit no serious evidence of damage or distress.

d. Reservoir Area

About 60% of the impoundment is gently sloping, grassed shoreline. The remaining 40% is moderate to steep and no evidence of slope instability was readily apparent.

The original impoundment has been reduced in size with dumped rock rubble from the excavation for the bank building. Additional material dumped into the impoundment has separated off a small portion of the upstream end of the pond.

e. Downstream Channel

The dam does not have a conventional downstream channel. Spillway discharge is carried off through 272 feet of 6 foot diameter concrete culvert beneath the bank parking lot. This culvert discharges into another 6 foot diameter concrete culvert which lies under U.S. Route 80.

3.2 Evaluation

Based on the visual inspection the dam appears to be functioning adequately. Some maintenance is in order and recommendations are presented in subsequent sections. The impoundment slopes show no apparent signs of instability and are not believed a potential hazard to the dam.

## SECTION 4: OPERATIONAL PROCEDURES

### 4.1 Procedures

Highland Lake is presently used to impound water for esthetic reasons only. The lake level is normally maintained by unregulated discharge over the service spillway in the right abutment. The other spillway releases excess flow during storms.

The low level outlet is inoperable and the impoundment, therefore, cannot be drained.

### 4.2 Maintenance of the Dam

There is no program of regular inspection and maintenance of the dam and appurtenant structures. Operation and maintenance is the responsibility of the New Jersey Bank, owner of the dam. At present, no records of operation and maintenance are kept.

### 4.3 Maintenance of Operating Facilities

The low level outlet gate valve is inoperable. No known maintenance of the valve has been made to keep the valve operable. The outlet pipe has not received maintenance.



#### 4.4

#### Evaluation

A formalized program of periodic inspection by an experienced party should be initiated and documentation recorded. If the dam is to continue to function in its present capacity the low level outlet and gate valve should be restored to an effective operational capacity.



## SECTION 5: HYDRAULIC/HYDROLOGIC

### 5.1 Evaluation of Features

#### a. Design

The drainage area above the Highland Lake Dam on the Slippery Rock Brook is approximately 0.76 square miles. A drainage map of the watershed of Highland Lake damsite is presented on Plate 1, Appendix D.

The topography within the basin varies from foot-hills type terrain in the upper section to generally hilly in the lower section. Elevations range from approximately 235 feet above mean sea level at the damsite to over 495 feet above mean sea level in the upper end of the watershed. U.S. Highway 80 is about a quarter mile downstream from the Highland Lake Dam.

Land use patterns within the watershed are mostly urban with some forested lands in the hilly section of the basin. Most of the urban areas are located near the rim of the reservoir and in the lower elevation portion of the watershed.

The evaluation of the hydraulic and hydrologic features of Highland Lake Dam was based on criteria set forth in the Corps guidelines and additional guidance provided by the Philadelphia District, Corps of Engineers. The Probable Maximum Flood (PMF) was calculated from the Probable Maximum Precipitation using Hydrometeorological Report No. 33 with standard reduction factors. Due to the small drainage area of

1

this dam, the SCS triangular hydrograph, transformed to a curvilinear hydrograph, was adopted for developing the unit hydrograph. The derived unit hydrograph is presented in Appendix D.

Initial and infiltration loss rates were applied using SCS procedure to the Probable Maximum Storm rainfall to obtain rainfall excesses. The rainfall excesses were then applied to the unit hydrograph to obtain the PMF hydrograph utilizing program HEC-1.

The computed peak discharge of the PMF and one-half the PMF are 3,826 cfs and 1,913 cfs, respectively.

0

Both the PMF and one-half the PMF inflow hydrographs were routed through the reservoir by the Modified Puls Method, also utilizing computer program HEC-1. The peak outflow discharges for the PMF and one-half the PMF are 3,793 cfs and 1,889 cfs, respectively. Both the PMF and one-half the PMF result in overtopping of the dam.

The stage-outflow relation for the spillway was prepared from field notes, sketches and limited construction drawings. The reservoir stage-capacity data were based on the U.S.G.S. quadrangle topographic maps in combination with data given in the National Dam Safety Inventory Table. Reservoir storage capacity include for surcharge levels exceeding the top of the dam and the spillway rating curve assumed that the dam remains intact during routing. In the routing computations, the discharge through outlet facilities was excluded due to its being inoperable. The spillway rating curve and the reservoir capacity curve are presented in Plates 2 and 3 of Appendix D, respectively.

b. Experience Data

No records of reservoir stage or spillway discharge are maintained for this site. However, according to interviews with local residents, the maximum reservoir level was never higher than the dam crest.

c. Visual Observation

The small watershed and reservoir is located in a well developed urban area. There is no evidence of excessive sedimentation due to recent developments in the drainage basin which could cause a sudden increase in sediment load, which may pose danger to the dam.

d. Overtopping Potential

As indicated in Section 5.1-a., both the Probable Maximum Flood and one-half the Probable Maximum Flood, when routed through Highland Lake Reservoir result in overtopping of the dam. The PMF and one-half the PMF overtopped the dam by 2.00 feet and 0.60 feet, respectively.

The spillway is only capable of passing a flood equal to approximately thirty-six percent of the PMF without overtopping the dam. Since one-half the PMF is the minimum Spillway Design Flood (SDF) for this dam, according to the Recommended Guidelines for Safety Inspection of Dams by the Corps of Engineers, the spillway capacity of the Highland Lake Dam is considered "Inadequate".

## SECTION 6: STRUCTURAL STABILITY

### 6.1 Evaluation of Structural Stability

#### a. Visual Observations

At the time of the inspection there were no readily apparent signs of instability in the structure. The abutments also appeared structurally competent. The spillways did not exhibit visual evidence of misalignment or structural cracking.

#### b. Design and Construction Data

No design computations were uncovered during the report preparation phase. No cross sections of the original masonry were available. The dimensions of the masonry wall, and extent of earthfill behind the wall, are undefined. No construction records or as-builts were available.

#### c. Operating Records

No operating records are available relating to the stability of the dam. The structure has apparently served satisfactorily since it was repaired in 1945.

#### d. Post-Construction Changes

It is not clear, from available drawings, just what the original section consisted of. A flood wave, caused by failure of an upstream dike during a storm in 1945, overtopped the dam and wingwalls eroding the soil in the abutments down

to bedrock. Damage to the structure, if any, was not reported. Repairs to the structure were undertaken in 1945, however, the plans do not shed any light on the original cross section.

f. Seismic Stability

A prominent joint set exposed in the left abutment areas strikes N5°E, dips 80°SE and has a joint spacing of 1 to 3 feet. This joint set parallels a fault, mapped by others, about one-half mile east of the dam. The dam is located in Seismic Zone 1, as defined in Recommended Guidelines For Safety Inspection of Dams as prepared by the Corps of Engineers. In general, projects located in Seismic Zones 0, 1 and 2 may be assumed to present no hazard from earthquake, provided the static stability conditions are satisfactory and conventional safety margins exist.



## SECTION 7: ASSESSMENT/REMEDIAL MEASURES

### 7.1 Dam Assessment

#### a. Safety

The dam has been inspected visually and a review has been made of the available engineering data. This assessment is subject to the limitations inherent in the visual inspection procedures stipulated by the Corps of Engineers for a Phase I report.

Highland Lake Dam does not have an adequate spillway capacity to pass the PMF or one-half of the PMF without overtopping. The dam's present spillway capacity can pass only about 36 percent of the PMF.

No definitive statement pertaining to the safety of the dam can be made without determination of the cross sectional dimensions of the dam and acquisition of the engineering properties of the masonry and earthfill section. The present dam, however, has performed adequately since its repair in 1945 without failure or evidence of instability. Further, it should be noted that the dam structure survived a flood wave in 1945 whose high water mark was later measured to be 2.75 feet above the dam's crest.

Nevertheless, the outstanding feature which provides substantial protection against loss of life and extensive property damage in the event of failure of Highland Lake Dam is the present parking lot immediately downstream of the dam. The parking lot, constructed in the early 1970's,

sits over a massive earthfill. A reinforced concrete retaining wall, 29.5 feet high, was constructed 25 to 30 feet from the dam and effectively encloses the structure. A 6 foot diameter concrete pipe culvert lies beneath the parking lot to carry dam discharges. In the event of a flood, the space between the dam and retaining wall will tend to fill with water until the culvert can accommodate the inflow or until the retaining wall is overtopped. Flooding of this space will produce hydrostatic pressure against the downstream face of the dam and increase the stability of the structure. In the event of actual failure of the structure, the retaining wall will act as a second dam, effectively limiting the release of the impoundment. It is quite possible that the culvert may even become clogged with debris from the failed structure and, thus, further retard the release of the impoundment, exclusive of that portion that might flow over the parking lot.

Therefore, even though the spillway capacity is inadequate and it is not possible, with the information which was available, to adequately assess the structural integrity of the dam, it is felt that the parking lot retaining wall and associated earthfill provides a substantial check against loss of life and excessive property damage by catastrophic failure of the dam.

Another inadequacy, at present, is the inability to lower the lake level due to inaccessibility to the control valve.

b. Adequacy of Information

The information and data uncovered is not adequate to perform a comprehensive, definitive evaluation of the dam's stability. Nevertheless, in view of the past performance of the dam, its present condition, and in light of the massive earthfill parking lot downstream it is not felt that additional information on the engineering properties of the embankment and foundation materials is necessary at this time.

c. Urgency

The valve box should be cleared of all debris. The low level outlet and the gate valve itself should be repaired or replaced within 3 months, to ensure a reliable operational drawdown facility.

A program for regularly observing seepage should be implemented within six months.

7.2 Remedial Measures

a. Alternatives

There is no real alternative to cleaning out the valve vault and making any necessary repairs to the control valve to make the low level outlet operable.


### 7.3      Recommendations

Normally, any water entering the valve box, through stem leakage or joint leakage or through the dam itself, should be allowed to drain through a separate line leading out of the valve box. Therefore, a drain should be provided through the wall of the valve box.


The deteriorated facing of the dam should be repaired.

PLATES






VICINITY MAP



### LEGEND



- |             |  |
|-------------|--|
| $\bar{R}b$  | BRUNSWICK FORMATION<br>RED SANDSTONE WITH INTERBEDS OF SOFT, RED SHALE |
| $\bar{R}bs$ | BASALT   |
| F           | FAULT  |

### GEOLOGIC MAP HIGHLAND LAKE DAM
















LINEN THREAD CO INC  
HIGHLAND LAKE DAM  
SHEET NO 2




OF WEST WINGWALL  
SCALE 1/4"=1'-0"








0+90 - 0+95.65



NOTE:  
CLASS B CONCRETE AS  
PER N.Y.S. STANDARD  
SPRCS 1041 SHALL BE  
USED IN ALL WALLS.



NS OF WEST WINGWALL

SCALE 1/2" = 1'-0"

APPENDIX A

CHECK LIST - VISUAL OBSERVATIONS

CHECK LIST - ENGINEERING, CONSTRUCTION  
MAINTENANCE DATA

CHECK LIST

Visual Inspection  
Phase I

Name Dam Highland Lake County Passaic State New Jersey Coordinators \_\_\_\_\_

Date(s) Inspection June 29, 1978 Weather Clear-Hot Temperature 85°F

Pool Elevation at Time of Inspection No gage M.S.L. Tailwater at Time of Inspection None M.S.L.  
W.S. at spillway crest.

Inspection Personnel:

(June 29, 1978)

Joe Siriani

(June 29, 1978)

William Flynn

(July 6, 1978)

Yin Au-Yeung

Henry King

Lynn Brown

David Kerkas

Robert B. Campbell Recorder

Owner Representative:

(June 29, 1978)

Tom Dinand, Maintenance Superintendent  
Bank of New Jersey



# CONCRETE/MASONRY DAMS

Highland Lake

Type - Curved Rock Masonry w/Brick Facing and then Gunite Coating

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SEEPAGE OR LEAKAGE	Considerable leakage from drain holes in gunite. Seepage overflowing out of outlet vault. Some seepage at foundation contact in lower third of left abutment and lower half of right abutment.	Install toe drains through brick to drain behind facing. Install collector and measuring device to measure seepage. Monitor seepage monthly to detect changes in quantity or quality of water.
STRUCTURE TO ABUTMENT/EMBANKMENT JUNCTIONS	Rock outcrops right and left abutment. Serious loosening of brick at abutment contact on right abutment just below mid-height of dam. Void in brick is 10 inches deep and extends 4 feet horizontally from abutment and 3 feet vertically.	Loose gunite coating should be removed and brick and gunite facings should be re-paired.
DRAINS	1" diameter holes and pipes in gunnite coating on about 4 foot horizontal spacing staggered on lines spaced about 2' vertically. Many drain holes flowing trickles of water.	See note above on toe drains.
WATER PASSAGES	See Spillways and Outlet Works.	
FOUNDATION	Dam founded directly on massive bedrock. Rock shows extensive fracturing. Large fractures on left abutment that may extend under dam.	

CONCRETE/MASONRY DAMS

Highland Lake

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURFACE CRACKS CONCRETE SURFACES	Considerable spalling of gunite coating, especially near right abutment. Gunite coating varies from 2 to more than 6 inches. Severe spalling at top of concrete cap.	Loose gunite should be re-moved and repaired. See note previous page.
STRUCTURAL CRACKING	Structure hidden by gunite. Crack of no significance is evident at bottom of concrete cap slab.	
VERTICAL AND HORIZONTAL ALIGNMENT	No evidence of movement of structure can be found.	
MONOLITH JOINTS	None visible.	
CONSTRUCTION JOINTS	None visible.	

EMBANKMENT

Highland Lake

Type - None

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURFACE CRACKS	N.A.	
UNUSUAL MOVEMENT OR CRACKING AT OR BEYOND THE TOE	N.A.	
SLOUGHING OR EROSION OF EMBANKMENT AND ABUTMENT SLOPES	N.A.	
VERTICAL AND HORIZON- TAL ALIGNMENT OF THE CREST	N.A.	
RIPRAP FAILURES	N.A.	

# EMBRANKMENT

Highland Lake

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
JUNCTION OF EMBANKMENT AND ABUTMENT, SPILLWAY AND DAM	N.A.	
ANY NOTICEABLE SEEPAGE	N.A.	
STAFF AND GAGE RECORDER	N.A.	
DRAINS	N.A.	

# OUTLET WORKS

Highland Lake

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CRACKING AND SPALLING OF CONCRETE SURFACES IN OUTLET CONDUIT	Outlet works abandoned. Was 12" C.I. pipe outlet with valve in concrete vault. Leakage or seepage is flowing from vault opening. Concrete in vault is sound.	Outlet works should be re-paired and put back into use. Small drain hole may need to be installed to allow seepage to drain from vault.
INTAKE STRUCTURE	Submerged and not visible. Cannot be inspected.	
OUTLET STRUCTURE	Outlet vault is filled to within one foot of top with 1/2-3/4" pebbles.	Pebbles should be cleaned out of vault and a cover and lock should be installed on vault.
OUTLET CHANNEL	None.	
EMERGENCY GATE	None.	



UNGATED SPILLWAY

#2 - Service Spillway-Right Abutment

Highland Lake

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONCRETE WEIR	Broad crest spillway 5 feet long. Floor moderately spalled.	Spalled concrete should be repaired whenever depth exceeds 3-4 inches.
APPROACH CHANNEL	None - Water depth is very shallow in front of spillway.	
DISCHARGE CHANNEL	Nearly vertical natural rock down to paved apron between dam and headwall. No obstructions.	
BRIDGE AND PIERS	None.	

UNGATED SPILLWAY

#2 - Service Spillway-Right Abutment

Highland Lake

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONCRETE WEIR	Broad crest spillway 5 feet wide. Floor moderately spalled.	Spalled concrete should be repaired whenever depth exceeds 3-4 inches.
APPROACH CHANNEL	None - Water depth is very shallow in front of spillway.	
DISCHARGE CHANNEL	Nearly vertical natural rock down to paved apron between dam and headwall. No obstructions.	
BRIDGE AND PIERS	None.	

GATED SPILLWAY  
(None)

Highland Lake

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONCRETE SILL	N.A.	
APPROACH CHANNEL	N.A.	
DISCHARGE CHANNEL	N.A.	
BRIDGE AND PIERS	N.A.	
GATES AND OPERATION EQUIPMENT	N.A.	

## INSTRUMENTATION

Highland Lake

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
MONUMENTATION/SURVEYS	None	
OBSERVATION WELLS	None	
WEIRS	None	
PIEZOMETERS	None	
OTHER	None	

# RESERVOIR

Highland Lake

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SLOPES	Varies. 60% is nearly flat to gently sloping with grassed lawn coverage for park. 40% steeply sloping rocky bank to about 20 feet height. All slopes appear stable.	
SEDIMENTATION	Extent of existing sedimentation unknown. Upstream lagoon constructed during building of bank will effectively stop further sedimentation.	
Shoreline Structures	No dwellings or structures are on shorelines. Bank of New Jersey owns property around lake for many hundreds of feet from shoreline.	
Use	Aesthetic - Scenic only. Area east of lake has been developed into a park.	
Operation	None - Water level is not regulated. Nature let to take its course.	



# DOWNSTREAM CHANNEL

Highland Lake

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONDITION (OBSTRUCTIONS, DEBRIS, ETC.)	Watercourse consists of a 272 feet long by 6 feet diameter concrete pipe culvert under bank parking lot, then concrete lined rectangular channel to 6' diameter culvert under Highway 80.	
SLOPES	Not Applicable.	
APPROXIMATE NUMBER OF HOMES AND POPULATION	No dwellings or buildings exist between the dam and Highway 80.	

CHECK LIST  
ENGINEERING DATA

DESIGN, CONSTRUCTION, OPERATION

Highland Lake Dam

ITEM	REMARKS
PLAN OF DAM	None available.
REGIONAL VICINITY MAP	Available.
CONSTRUCTION HISTORY	None available.
TYPICAL SECTIONS OF DAM	None available.
HYDROLOGIC/HYDRAULIC DATA	None available.
OUTLETS - PLAN	)
- DETAILS	) None Available.
- CONSTRAINTS	)
- DISCHARGE RATINGS	)
RAINFALL/RESERVOIR RECORDS	None Available.

CHECK LIST  
ENGINEERING DATA

DESIGN, CONSTRUCTION, OPERATION  
(Continued)

Highland Lake Dam

ITEM	REMARKS
DESIGN REPORTS	None available.
GEOLOGY REPORTS	None available.
DESIGN COMPUTATIONS	)
HYDROLOGY & HYDRAULICS	) None available.
DAM STABILITY	)
SEEPAGE STUDIES	)
MATERIALS INVESTIGATIONS	)
BORING RECORDS	) None available.
LABORATORY	)
FIELD	)
POST-CONSTRUCTION SURVEYS OF DAM	The dam was surveyed and drawings of repairs to the toe of the dam and to the abutments were prepared in 1945 and are available from New Jersey Department of Environmental Protection.
BORROW SOURCES	Unknown.
SPILLWAY - PLAN	)
- SECTIONS	) None available.
- DETAILS	)

CHECK LIST  
ENGINEERING DATA

DESIGN, CONSTRUCTION, OPERATION  
(Continued)

Highland Lake Dam

ITEM	REMARKS
OPERATING EQUIPMENT PLANS AND DETAILS	) None available. )
MONITORING SYSTEMS	None available.
MODIFICATIONS	Repairs and modifications including extending the spillway, gunniting both faces of the masonry dam, installing toe underpinning, and rebuilding abutment walls was done in 1945.
HIGH POOL RECORDS	None available.
POST-CONSTRUCTION ENGINEERING STUDIES AND REPORTS	None available.
PRIOR ACCIDENTS OR FAILURE OF DAM - DESCRIPTION - REPORTS	A severe storm in 1945 caused an upstream dike to fail producing a flood wave that overtopped and washed away the topsoil on both abutments.
MAINTENANCE, OPERATION RECORDS	None available.

APPENDIX B

PHOTOGRAPHS

(All photos were taken on June 29, 1978.)



Highland Lake Dam



Photo 1 - View along crest of dam from left abutment showing main spillway and service spillway on right abutment.



Photo 2 - View of dam and left abutment from upstream right shoreline.

Highland Lake Dam



Photo 3 - View of dam and bank parking lot below dam.




Photo 4 - View of dam from bank parking lot. Dam is partially hidden by guard railing on parking lot retaining wall.

Highland Lake Dam



Photo 6 - View of joint in rock located in left abutment of dam.



Photo 5 - View showing dam, left abutment rock and abandoned outlet pipe and concrete vault.

Highland Lake Dam




Photo 8 - Drain hole in gunitite facing on downstream face of dam.




Photo 7 - View showing dam, right abutment rock, downstream parking lot retaining wall and service spillway discharge down rock abutment.



Highland Lake Dam




Photo 10 - Exposed brick facing under spalled and displaced gunite facing at right abutment.



Photo 9 - Drain holes and exposed wire mesh under spalled gunite.



Highland Lake Dam




Photo 11 - Main spillway and right shoreline.




Photo 12 - Service spillway from downstream.

Highland Lake Dam



Photo 13 - View of dam, bottom slab under main spillway, retaining wall and discharge culvert under parking lot.




Photo 14 - Inlet and 6 ft. diameter concrete pipe discharge culvert.

Highland Lake Dam



Photo 16 - Inlet to 6 ft. diameter culvert  
under Highway 80.




Photo 15 - Outlet structure for parking lot  
culvert.

Highland Lake Dam



Photo 17 - View of Highland Lake from right abutment showing  
barrage built from bank excavation and forming  
small upper impoundment.

APPENDIX C

SUMMARY OF ENGINEERING DATA



CHECK LIST  
HYDROLOGIC AND HYDRAULIC DATA  
ENGINEERING DATA

Name of Dam: Highland Lake Dam  
Drainage Area: 0.76 square miles  
Elevation Top Normal Pool (Storage Capacity): 235.22 (49 AF)  
Elevation Top Flood Control Pool (Storage Capacity): Not applicable  
Elevation Maximum Design Pool: 236.24  
Elevation Top of Dam: 237.82

SPILLWAY CREST:

- a. Elevation: 235.22
- b. Type: Overflow
- c. Width: 4 feet (right end spillway); 10 feet (spillway at the mid-section)
- d. Length: 44 feet (total notch length)
- e. Location Spillover: One at right end and one at mid-section of dam
- f. Number and Type of Gates: None

OUTLET WORKS:

- a. Type: 12-inch cast iron pipe (inoperable)
- b. Location: Left side of the dam
- c. Entrance Inverts: Not applicable
- d. Exit Inverts: Not applicable
- e. Emergency Draindown Facilities: Not applicable

HYDROMETEOROLOGICAL GAGES: (None)


- a. Type: \_\_\_\_\_
- b. Location: \_\_\_\_\_
- c. Records: \_\_\_\_\_

MAXIMUM NON-DAMAGING DISCHARGE: 800 cfs (Estimated) This is the maximum discharge that will not cause damage downstream from the dam.


APPENDIX D

HYDROLOGIC COMPUTATIONS

PLATE 1 APPENDIX D



HIGHLAND LAKE DAM  
DRAINAGE BASIN



HIGHLAND LAKE DAM  
SPILLWAY & OVERTOP RATING CURVE



NEW JERSEY (STATE) DAM SAFETY INSPECTION


SHEET NO. 1 OF

HIGHLAND LAKE DAM

JOB NO. 1212-001


SPILLWAY & OVERTOP RATING CURVE

BY MAS DATE 7-14



ELEV.	Head mopping Crest ft	H <sub>1</sub>	H <sub>2</sub>	H <sub>3</sub>	L <sub>1</sub>	L <sub>2</sub>	L <sub>3</sub>	C <sub>1</sub>	C <sub>2</sub>	C <sub>3</sub>	
235.22	0	0									0
235.72	0.5	0.5	0		44			3.03			47
236.72	1.5	1.5	1.0		44	95		3.03	3.03		533
237.82	2.6	2.6	2.1	0	44	95		3.03	3.03		1435
238.82	3.6	3.6	3.1	1.0	44	95	0	3.03	3.03	3.03	2506
240	4.78	4.78	4.28	2.18	44	95	0	3.03	3.03	3.03	4020





HIGHLAND LAKE DAM  
RESERVOIR AREA-CAPACITY CURVE

NEW JERSEY (STATE) DAM SAFETY INSPECTION

SHEET NO. 1 OF

HIGHLAND LAKE DAM

JOB NO. 1212-001

RESERVOIR AREA - CAPACITY DATA

BY JAS DATE 7-17-

## HIGHLAND LAKE DAM

## RESERVOIR AREA - CAPACITY DATA

Maximum Storage = 55 Acre-feet,

Normal Storage = 49 A-F,

Reservoir Surface Area = 5.73 Acres (from 7½ USGS topo map) El = 235.22 (assumed to be at Spillway crest).

Elev. Ft.	Reservoir Surface Area Acres	Reservoir Volume AC-FT	Remarks
235.22	5.73	49	The normal volume of 49 acres is assumed to be at Spillway El 235.22
236.24	6±	55	The elevation of maximum storage of 55 AC-FT is obtained by assuming a reservoir surface area of 6± acres.
237.82	6±	64.5	The volume figures are extended by assuming the same area of 6± acres
240	6±	77.6	

NEW JERSEY (STATE) DAM SAFETY INSPECTION

SHEET NO. 1 OF 1

HIGHLAND LAKE DAM #5

JOB NO. 1212-001

UNIT HYDROGRAPH

BY KLB

DATE 7-11-

## UNIT HYDROGRAPH - HIGHLAND LAKE DAM

a) DRAINAGE AREA = 0.76 SQ. MI.

b)  $L = 0.91$  MILES (FROM PAGE 2)


c)  $T_c = 0.27$  HR (FROM PAGE 2)

d) ASSUME  $D = 0.10$  HR  $< \frac{T_c}{2}$

e)  $T_p = \frac{D}{2} + 0.6 \times T_c = 0.05 + 0.6 \times 0.27$   
 $= 0.21$  HR

f)  $T_b = 2.67 \times T_p = 0.56$  HR

g)  $Q_p \text{ cfs} = \frac{484 A (\text{SQ. MI})}{T_p (\text{HR})} = \frac{484 \times 0.76}{0.21} = 1752 \text{ CFS}$





ENGINEERING CONSULTANTS, INC.

NEW JERSEY (STATE) DAM SAFETY INSPECTION SHEET NO. 2 OF

HIGHLAND LAKE DAM, #5

JOB NO. 1212-001

DETERMINE BASIN PARAMETERS

BY HLB DATE

lin

DETERMINE LENGTH OF STREAM

FROM U.S.G.S QUAD SHEETS

$$L = 2.4" \times \frac{24000}{12 \times 5280} = 0.91 \text{ MILES} = 4800 \text{ FT}$$

DETERMINE BASIN SLOPE

$$\Delta H = 495 - 235 = 260 \text{ FT.}$$

DETERMINE TIME OF CONCENTRATION

$$T_c = \left( \frac{11.9 L^3}{\Delta H} \right)^{0.385} = \left( \frac{11.9 \times 0.91^3}{260} \right)^{0.385}$$

$$= 0.27 \text{ HR.}$$

CI-4

## ENGINEERING CONSULTANTS, INC.

NEW JERSEY (STATE) DAM SAFETY INSP. SHEET NO. 3 OF 4

HIGHLAND LAKE DAM #5

JOB NO. 1212-001-1


UNIT HYDROGRAPH

BY KLB DATE 2-11-71

h) CURVILINEAR HYDROGRAPH

TIME RATIO $T/T_p$	DISCHARGE RATIO $q/q_p$	UNIT GRAPH	
		TIME $T$ (HR)	DISCHARGE $q$ (CFS)
0	0	0	0
0.1	0.015	0.021	26
0.2	0.075	0.042	131
0.3	0.16	0.063	280
0.4	0.28	0.084	491
0.5	0.43	0.105	753
0.6	0.60	0.126	1051
0.7	0.77	0.147	1349
0.8	0.89	0.168	1559
0.9	0.97	0.189	1699
1.0	1.00	0.210	1752
1.1	0.98	0.23	1717
1.2	0.92	0.25	1612
1.3	0.84	0.27	1472
1.4	0.75	0.29	1314
1.5	0.66	0.32	1156
1.6	0.56	0.34	981
1.8	0.42	0.38	736
2.0	0.32	0.42	561
2.2	0.24	0.46	420
2.4	0.18	0.50	315
2.6	0.13	0.55	228
2.8	0.098	0.59	172
3.0	0.075	0.63	131
3.5	0.036	0.74	63
4.0	0.018	0.84	32
4.5	0.009	0.95	16
5.0	0.004	1.05	7





HIGH LAND LAKE DAM  
0.10 HR. UNIT HYDROGRAPH

PMP DRAINAGE HIGHLAND LAKE DAM  
Probable Maximum Precipitation

PROBABLE MAXIMUM FLOOD CALCULATION (PMP)

DRAINAGE = 0.16 sq. mi.

From Hydrometeorological Report #33 "Seasonal Variation of the Probable Maximum Precipitation East of the 105<sup>th</sup> Meridian for Areas from 10 to 1,000 Square Miles and Duration of 6, 12, 24 and 48 Hours", 1966

For D.A. = 10 sq. mi.

6 hour rainfall duration.

PMP = 25.0" for Zone "6" at this Basin.

Since D.A. < 10 sq. mi., No area reduction to be applied.

PMP Values for various rain fall duration

<u>Duration</u>	<u>PMP (inch)</u>
6 hr	25.0"
12 hr	27.25
24 hr	29.25
48 hr	31.50

PMP values are reduced by 20% to account for misalignment

of Basin and storm Isohyets

<u>Duration</u>	<u>PMP</u>
6 hr	20.0"
12 hr	21.8
24 hr	23.4
48 hr	25.2

Can be neglected.

ECI-4 ENGINEERING CONSULTANTS, INC.

NEW JERSEY DAM SAFETY INSPECTION (DUP)  
 PMF DERIVATION - HIGHLAND LAKE DAM  
 PROBABLE MAXIMUM PRECIPITATION

SHEET NO. \_\_\_\_\_ OF \_\_\_\_\_

JOB NO. 1212

BY YIN DATE \_\_\_\_\_

0.76 SQ. MI.

PMP. PMF DERIVATION.

1) SOIL GROUP "C", & AMC = II.

2) CN = 85.

MIN LOSS RATE FOR ABOVE CONDITION IS 0.12"/hr.

OR 0.04"/1/2 hr.

FOR CN = 85,

S = 1.76 in the

$$\text{eg. } Q = (P - 0.2S)^2 / P + 0.85$$

$$\text{OR } Q = \frac{(P - 0.362)^2}{P + 1.408}$$

NEW JERSEY DAM SAFETY INSPECTION (AEP) SHEET NO. 1 OF

PMF DERIVATION - HIGHLAND LAKE DAM JOB NO. 1212-001-1

DIRECT RUNOFF

BY KLB DATE 7-21-78

## DIRECT RUNOFF INCREMENTS FOR COMPUTING - PMF

TIME ENDING (HR.)	INCREMENTAL DESIGN RAINFALL (IN)	ACCUMULATIVE DESIGN RAINFALL (IN)	DIRECT RUNOFF		INCREMENTAL LOSS (IN)
			ACCUMULATIVE (IN)	INCREMENTAL (IN)	
0.10	0.20	0.20	0.00	0.00	0.00
0.20	0.20	0.40	0.00	0.00	0.00
0.30	0.20	0.60	0.03	0.00	0.03
0.40	0.20	0.80	0.09	0.06	0.14
0.50	0.20	1.00	0.17	0.08	0.12
0.60	0.20	1.20	0.28	0.11	0.09
0.70	0.20	1.40	0.39	0.11	0.09
0.80	0.20	1.60	0.52	0.13	0.07
0.90	0.20	1.80	0.65	0.13	0.07
1.00	0.20	2.00	0.80	0.15	0.05
1.10	0.24	2.24	0.98	0.18	0.06
1.20	0.24	2.48	1.16	0.18	0.06
1.30	0.24	2.72	1.36	0.20	0.04
1.40	0.24	2.96	1.56	0.20	0.04
1.50	0.24	3.20	1.76	0.20	0.04
1.60	0.24	3.44	1.97	0.21	0.03
1.70	0.24	3.68	2.18	0.21	0.03
1.80	0.24	3.92	2.39	0.21	0.03
1.90	0.24	4.16	2.60	0.21	0.03
2.00	0.24	4.40	2.82	0.22	0.02
2.10	0.30	4.70	3.10	0.28	0.02
2.20	0.30	5.00	3.37	0.27	0.03
2.30	0.30	5.30	3.65	0.28	0.02
2.40	0.30	5.60	3.93	0.28	0.02
2.50	0.30	5.90	4.21	0.28	0.02
2.60	0.30	6.20	4.50	0.29	0.01*
2.70	0.30	6.50	4.78	0.29	0.01
2.80	0.30	6.80	5.07	0.29	0.01
2.90	0.30	7.10	5.35	0.29	0.01
3.00	0.30	7.40	5.64	0.29	0.01

\* MINIMUM LOSS RATE =  $0.12"/HR = 0.012"/.1HR$  SAY  $0.01"/.1HR$   
 (AFTER THIS RATE IS REACHED, ABANDON CURVE FOR CONSTANT LOSS)



# ENGINEERING CONSULTANTS, INC.

NEW JERSEY DAM SAFETY INSPECTION - (DEP) SHEET NO. 2 OF  
 PMF DERIVATION - HIGHLAND LAKE DAM JOB NO. 1212-201-1  
 DIRECT RUNOFF CONT. BY KLB DATE 7-24

## DIRECT RUNOFF INCREMENTS FOR COMPUTING - PMF

TIME ENDING (HR)	INCREMENTAL DESIGN RAINFALL (IN)	ACCUMULATIVE DESIGN RAINFALL (IN)	DIRECT RUNOFF		INCREMENTAL LOSS
			ACCUMULATIVE (IN)	INCREMENTAL (IN)	(IN)
3.10	0.75	8.15	6.36	0.74	0.01
3.20	0.75	8.90	7.09	0.74	0.01
3.30	0.75	9.65	7.82	0.74	0.01
3.40	0.75	10.40	8.55	0.74	0.01
3.50	0.75	11.15	9.28	0.74	0.01
3.60	0.90	12.05	10.17	0.89	0.01
3.70	0.75	12.80	10.91	0.74	0.01
3.80	0.75	13.55	11.65	0.74	0.01
3.90	0.75	14.30	12.39	0.74	0.01
4.00	0.73	15.03	13.11	0.72	0.01
4.10	0.28	15.31	13.38	0.27	0.01
4.20	0.28	15.59	13.66	0.27	0.01
4.30	0.28	15.87	13.94	0.27	0.01
4.40	0.28	16.15	14.21	0.27	0.01
4.50	0.28	16.43	14.49	0.27	0.01
4.60	0.28	16.71	15.00	0.27	0.01
4.70	0.28	16.99	15.05	0.27	0.01
4.80	0.28	17.27	15.32	0.27	0.01
4.90	0.28	17.55	15.84	0.27	0.01
5.00	0.28	17.83	15.88	0.27	0.01
5.10	0.22	18.05	16.10	0.21	0.01
5.20	0.22	18.27	16.32	0.21	0.01
5.30	0.22	18.49	16.53	0.21	0.01
5.40	0.22	18.71	16.75	0.21	0.01
5.50	0.22	18.99	17.03	0.21	0.01
5.60	0.22	19.15	17.19	0.21	0.01
5.70	0.22	19.37	17.41	0.21	0.01
5.80	0.22	19.59	17.63	0.21	0.01
5.90	0.22	19.81	17.84	0.21	0.01
6.00	0.22	20.03	18.06	0.21	0.01

\* MINIMUM LOSS RATE = 0.12"/HR = 0.012"/HR SAY 0.01"/HR  
 (AFTER THIS RATE IS REACHED, RANDOM CURVE FOR CONSTANT LOSSES)



HEC-1 - COMPUTATIONS

# ENGINEERING CONSULTANTS, INC.

NEW JERSEY DAM SAFETY INSPECTION - (DEP)

SHEET NO. 1 OF

INPUT FOR HEC-1, HIGHLAND LAKE DAM

JOB NO. 1212-001-1

Y2 - Y3 CARD DATA

BY HLB

DATE 7-21-78

## INPUT TO HEC-1 (FROM CURVES)

	#	ELEV (FT)	Y2 STORAGE (AC-FT)	Y3 DISCHARGE (CFS)
SPILLWAY CREST	1	235.22	49.0	0.
	2	235.87	52.8	100.
	3	236.52	56.5	400.
	4	237.17	60.4	840.
	5	237.50	62.5	1100.
TOP OF DAM	6	237.82	64.5	1400.
	7	238.20	66.6	1770.
	8	238.50	68.5	2100.
	9	239.00	71.4	2660.
	10	240.00	77.2	4000.

\*\*\*\*\*  
HEC-1 VERSION DATED JAN 1975  
\*\*\*\*\*

\*\*\*\*\*  
DAM SAFETY INSPECTION - NEW JERSEY STATE  
HIGHLAND LAKE DAM  
PNE FLOOD ROUTING  
\*\*\*\*\*

JOB SPECIFICATION  
NO NHR NMN IDAY LHR JMIN METRC IPLT IPRT NSTAN  
80 0 6 0 0 0 0 0 0 0  
JUPEN NMT  
3  
0

\*\*\*\*\*

SUB-AREA RUNOFF COMPUTATION

INPUT UNIT HYDROGRAPH DERIVED FROM SCS METHOD

ISTAQ ICOMP IECUN IIAPL JPLT JPRT INAME  
5 0 0 0 0 0 1

HYDROGRAPH DATA  
IHYDG IUHG TAREA SNAP TRSDA TRNSPC RATIO ISNOW ISAME LOCAL  
0 -1 0.76 0.00 0.76 0.00 0.000 0 0 0

PRECIP DATA  
NP STORM URAJ DAK  
60 0.00 0.00 0.00  
PRECIP PATTERN  
0.00 0.00 0.06 0.08 0.11 0.11 0.13 0.13 0.13 0.15  
0.18 0.20 0.20 0.20 0.21 0.21 0.21 0.21 0.21 0.22  
0.28 0.28 0.28 0.28 0.29 0.29 0.29 0.29 0.29 0.29  
0.74 0.74 0.74 0.74 0.89 0.89 0.74 0.74 0.74 0.74  
0.27 0.27 0.27 0.27 0.27 0.27 0.27 0.27 0.27 0.27  
0.21 0.21 0.21 0.21 0.21 0.21 0.21 0.21 0.21 0.21

LOSS DATA  
STKR DLTGR RTIOL ERIN STRKS RTIOL STKTL CNSTL ALSTM RTIMP  
0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00

0. 625. 1752. 1250. 625. 355. 150. 75. 80. 8.  
0. UNIT GRAPH TOTALS 4837. CFS OR 0.98 INCHES OVER THE AREA

RECESSION DATA  
STRTG= 0.00 GRSNE 0.00 RTIOL= 1.00

END-OF-PERIOD FLOW  
TIME RAIN EXCS COMP  
1 0.00 0.00 0.  
2 0.00 0.00 0.  
3 0.00 0.00 0.  
4 0.00 0.00 0.



5	0.08	0.08	57.
6	0.11	0.11	155.
7	0.11	0.11	283.
8	0.13	0.13	398.
9	0.13	0.13	480.
10	0.15	0.15	590.
11	0.18	0.18	609.
12	0.18	0.18	679.
13	0.20	0.20	766.
14	0.20	0.20	832.
15	0.20	0.20	894.
16	0.21	0.21	933.
17	0.21	0.21	957.
18	0.21	0.21	984.
19	0.21	0.21	1001.
20	0.22	0.22	1009.
21	0.28	0.28	1013.
22	0.27	0.27	1075.
23	0.28	0.28	1188.
24	0.28	0.28	1258.
25	0.28	0.28	1304.
26	0.29	0.29	1331.
27	0.29	0.29	1350.
28	0.29	0.29	1374.
29	0.29	0.29	1389.
30	0.29	0.29	1396.
31	0.74	0.74	1400.
32	0.74	0.74	1682.
33	0.74	0.74	2472.
34	0.74	0.74	3034.
35	0.74	0.74	3316.
36	0.89	0.89	3462.
37	0.74	0.74	3623.
38	0.74	0.74	3826.
39	0.74	0.74	3768.
40	0.74	0.74	3673.
41	0.27	0.27	3628.
42	0.27	0.27	3308.
43	0.27	0.27	2473.
44	0.27	0.27	1879.
45	0.27	0.27	1581.
46	0.27	0.27	1428.
47	0.27	0.27	1357.
48	0.27	0.27	1322.
49	0.27	0.27	1308.
50	0.27	0.27	1305.
51	0.21	0.21	1305.
52	0.21	0.21	1288.
53	0.21	0.21	1163.
54	0.21	0.21	1088.
55	0.21	0.21	1050.
56	0.21	0.21	1031.
57	0.21	0.21	1022.
58	0.21	0.21	1017.
59	0.21	0.21	1016.
60	0.21	0.21	1015.
61	0.00	0.00	1015.
62	0.00	0.00	884.
63	0.00	0.00	516.
64	0.00	0.00	2541.
65	0.00	0.00	132.



1001 SOUTH NAVAJO DENVER COLORADO 80223



	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	SUM
6-HOUR	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	17.98
24-HOUR	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	17.98
72-HOUR	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	17.98
TOTAL VOLUME	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	86965.

PEAK 3026.  
CFS 1447.  
INCHES 17.71  
AC-FT 718.

\*\*\*\*\*

# HYDROGRAPH ROUTING

## ROUTE HYDROGRAPH THROUGH HIGHLAND LAKE DAM

ISTAQ	ICOMP	IECON	IIAPE	JPLI	JPRI	INAME
5	1	0	0	2	0	1

GLOSS	CLOSS	AVG	AVG	AVG	AVG	AVG
0.0	0.000	0.00	0.00	0.00	0.00	0.00

NSTPS	NSTDL	LAG	APSKK	X	TSK	STORA
0	0	0	0.000	0.000	0.000	-1.

STORAGE=	49.	52.	56.	60.	64.	68.	71.	77.
OUTFLOW=	0.	100.	400.	840.	1100.	1400.	1770.	2100.

TIME	EOP	STOR	AVG	IN	EOP	OUT
1	49.	0.	0.	0.	0.	0.
2	49.	0.	0.	0.	0.	0.
3	49.	0.	0.	0.	0.	0.
4	49.	0.	0.	0.	0.	0.
5	49.	18.	96.	21.	3.	3.
6	49.	51.	219.	60.	60.	60.
7	51.	53.	341.	140.	140.	140.
8	53.	55.	439.	230.	230.	230.
9	55.	56.	515.	404.	404.	404.
10	56.	57.	577.	514.	514.	514.
11	57.	58.	642.	595.	595.	595.
12	58.	59.	782.	576.	576.	576.
13	59.	60.	799.	784.	784.	784.
14	60.	60.	883.	834.	834.	834.
15	60.	60.	913.	883.	883.	883.
16	60.	60.	913.	883.	883.	883.

1001 SOUTH NAVAJO, DENVER, COLORADO 80222



17	61.	945.	925.
18	61.	971.	956.
19	61.	993.	941.
20	61.	1005.	997.
21	61.	1014.	1008.
22	61.	1047.	1035.
23	62.	1131.	1100.
24	63.	1223.	1194.
25	63.	1281.	1260.
26	63.	1317.	1304.
27	64.	1340.	1332.
28	64.	1362.	1395.
29	64.	1382.	1375.
30	64.	1393.	1389.
31	64.	1398.	1396.
32	65.	1541.	1518.
33	67.	2077.	1987.
34	71.	2753.	2660.
35	73.	3175.	3163.
36	74.	3389.	3384.
37	75.	3543.	3539.
38	75.	3725.	3720.
39	76.	3795.	3793.
40	75.	3718.	3720.
41	75.	3650.	3652.
42	74.	3468.	3472.
43	72.	2890.	2904.
44	69.	2176.	2235.
45	66.	1750.	1805.
46	65.	1504.	1552.
47	64.	1392.	1418.
48	64.	1340.	1356.
49	64.	1315.	1325.
50	63.	1307.	1311.
51	63.	1305.	1307.
52	63.	1287.	1291.
53	63.	1215.	1233.
54	62.	1125.	1151.
55	62.	1069.	1090.
56	62.	1041.	1056.
57	61.	1026.	1036.
58	61.	1020.	1025.
59	61.	1016.	1019.
60	61.	1015.	1017.
61	61.	1015.	1016.
62	61.	950.	971.
63	59.	700.	791.
64	57.	585.	553.
65	55.	188.	532.
66	54.	88.	209.
67	53.	58.	124.
68	52.	15.	88.
69	51.	4.	71.
70	51.	0.	57.
71	50.	0.	46.
72	50.	0.	37.
73	50.	0.	29.
74	49.	0.	24.
75	49.	0.	19.
76	49.	0.	15.
77	49.	0.	12.

1001 SOUTH NAVALO, DENVER, COLORADO 80223

78	49.	0.	10.
79	49.	0.	8.
80	49.	0.	6.
SUM			86942.

PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
3793.	1440.	1086.	1086.	86942.
	17.63	17.73	17.73	17.73
	714.	718.	718.	718.

CFS  
INCHES  
AC-FT

FOFI

1901 SOUTH NAVAJO LIFNER, CO., ORALID 90223

RUNOFF SUMMARY: AVERAGE FLOW

HYDROGRAPH AT ROUTED TO	PEAK	6-HOUR AVERAGE FLOW			72-HOUR AVERAGE FLOW		AREA
		6-HOUR	24-HOUR	72-HOUR	72-HOUR	AREA	
5	3826.	1447.	1087.	1087.	1087.	0.76	0.76
5	3793.	1440.	1086.	1086.	1086.	0.76	0.76

TEOTL

1901 SOUTH NAVAJO, DENVER, COLORADO 80223

\*\*\*\*\*  
 HEC-1 VERSION DATED JAN 1973  
 \*\*\*\*\*

DAM SAFETY INSPECTION - NEW JERSEY STATE  
 HIGHLAND LAKE DAM  
 ONE HALF PMF FLOOD ROUTING

JOB SPECIFICATION  
 INJ NHR INMIN IDAY IMR IMIN METRC IPLT IPRT NSTAN  
 80 0 6 0 0 0 0 0 0 0 0  
 JOPEN NMT  
 3 0

\*\*\*\*\*

SUB-AREA RUNOFF COMPUTATION

INPUT UNIT HYDROGRAPH DERIVED FROM SCS METHOD

ISTAQ ICOMP IECON ITAPL JPLT JPRT INAME  
 5 0 0 0 0 0 1

HYDROGRAPH DATA  
 INHVG IUHG TAREA SNAP IRSUA INSPCL RATIO ISNOW ISAME LOCAL  
 0 -1 0.76 0.00 0.76 0.00 0.500 0 0 0

PRECIP DATA  
 NP STORM DAK  
 60 0.00 0.00 0.00  
 PNECIP PATTERN  
 0.06 0.08 0.11 0.11 0.13 0.13 0.15  
 0.18 0.20 0.20 0.21 0.21 0.21 0.22  
 0.23 0.27 0.28 0.28 0.29 0.29 0.29  
 0.74 0.74 0.74 0.74 0.74 0.74 0.74  
 0.27 0.27 0.27 0.27 0.27 0.27 0.27  
 0.21 0.21 0.21 0.21 0.21 0.21 0.21

LOSS DATA  
 STRKR DLTGR RTIOL ERAIN STRKS RTIOL STKTL CNSTL ALSMK RTIMP  
 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00

0. 625. 1752. 1250. 625. 325. 150. 75. 30. 5.  
 0. UNIT GRAPH TOTALS 4837. CFS OR 0.98 INCHES OVER THE AREA

STARTQ= 0.00 RECESION DATA  
 QRCSE= 0.00 RTIQR= 1.00

END-OF-PERIOD FLOW  
 TIME RAIN LACS COMP Q  
 1 0.00 0.00 0.  
 2 0.00 0.00 0.  
 3 0.00 0.00 0.  
 4 0.06 0.06 0.



5	0.08	0.08	37.
6	0.11	0.11	155.
7	0.11	0.11	285.
8	0.13	0.13	398.
9	0.13	0.13	480.
10	0.15	0.15	550.
11	0.18	0.18	605.
12	0.18	0.18	679.
13	0.20	0.20	766.
14	0.20	0.20	832.
15	0.20	0.20	894.
16	0.21	0.21	933.
17	0.21	0.21	957.
18	0.21	0.21	984.
19	0.21	0.21	1001.
20	0.22	0.22	1009.
21	0.28	0.28	1013.
22	0.27	0.27	1075.
23	0.28	0.28	1188.
24	0.28	0.28	1258.
25	0.28	0.28	1304.
26	0.29	0.29	1351.
27	0.29	0.29	1350.
28	0.29	0.29	1374.
29	0.29	0.29	1389.
30	0.29	0.29	1396.
31	0.74	0.74	1400.
32	0.74	0.74	1682.
33	0.74	0.74	2472.
34	0.74	0.74	3034.
35	0.74	0.74	3316.
36	0.89	0.89	3462.
37	0.74	0.74	3623.
38	0.74	0.74	3826.
39	0.74	0.74	3764.
40	0.74	0.74	3673.
41	0.27	0.27	3628.
42	0.27	0.27	3308.
43	0.27	0.27	2473.
44	0.27	0.27	1879.
45	0.27	0.27	1381.
46	0.27	0.27	1428.
47	0.27	0.27	1357.
48	0.27	0.27	1322.
49	0.27	0.27	1308.
50	0.27	0.27	1305.
51	0.21	0.21	1305.
52	0.21	0.21	1268.
53	0.21	0.21	1163.
54	0.21	0.21	1088.
55	0.21	0.21	1050.
56	0.21	0.21	1031.
57	0.21	0.21	1022.
58	0.21	0.21	1017.
59	0.21	0.21	1016.
60	0.21	0.21	1015.
61	0.00	0.00	1015.
62	0.00	0.00	884.
63	0.00	0.00	518.
64	0.00	0.00	294.
65	0.00	0.00	132.

100 SOUTH NAVALO, DENVER, COLORADO 80231



AD-A060 017


HARRIS ECI ASSOCIATES WOODBRIDGE NJ  
NATIONAL DAM SAFETY PROGRAM. HIGHLAND LAKE DAM (NJ00240), PASSA--ETC(U)  
AUG 78 R GERSHOWITZ

UNCLASSIFIED

DACW61-78-C-0124

NL


2 OF 2  
AD  
A0600 7



END  
DATE  
FILMED

12-78

DDC



MICROCOPY RESOLUTION TEST CHART  
NATIONAL BUREAU OF STANDARDS-1963-A



2	49.	0.	0.
3	49.	0.	0.
4	49.	0.	0.
5	49.	9.	1.
6	49.	48.	10.
7	50.	109.	30.
8	51.	170.	57.
9	52.	219.	69.
10	53.	257.	157.
11	54.	286.	224.
12	54.	321.	272.
13	55.	361.	317.
14	55.	399.	358.
15	56.	431.	395.
16	56.	456.	433.
17	57.	472.	458.
18	57.	485.	475.
19	57.	496.	488.
20	57.	502.	497.
21	57.	507.	503.
22	57.	523.	516.
23	57.	565.	547.
24	58.	611.	588.
25	58.	640.	621.
26	58.	658.	645.
27	58.	670.	661.
28	58.	681.	673.
29	59.	691.	684.
30	59.	696.	692.
31	59.	699.	696.
32	59.	770.	743.
33	61.	1038.	937.
34	63.	1376.	1252.
35	65.	1567.	1320.
36	66.	1694.	1467.
37	66.	1771.	1755.
38	67.	1862.	1844.
39	67.	1897.	1889.
40	67.	1859.	1864.
41	66.	1825.	1831.
42	66.	1734.	1749.
43	65.	1445.	1493.
44	62.	1088.	1174.
45	61.	865.	956.
46	60.	752.	819.
47	59.	696.	741.
48	59.	670.	695.
49	58.	627.	671.
50	58.	653.	660.
51	58.	652.	655.
52	58.	643.	647.
53	58.	607.	622.
54	58.	562.	584.
55	57.	534.	552.
56	57.	520.	532.
57	57.	513.	520.
58	57.	510.	518.
59	57.	508.	510.
60	57.	507.	508.
61	57.	507.	508.
62	57.	475.	467.



1301 SOUTH AVENUE, DENVER, COLORADO 80223

63	36.	350.	400.
64	55.	192.	299.
65	53.	94.	194.
66	53.	44.	119.
67	52.	19.	87.
68	51.	7.	72.
69	51.	2.	58.
70	50.	0.	47.
71	50.	0.	37.
72	50.	0.	30.
73	49.	0.	24.
74	49.	0.	19.
75	49.	0.	15.
76	49.	0.	12.
77	49.	0.	10.
78	49.	0.	8.
79	49.	0.	6.
80	49.	0.	5.
SUM		43462.	
PEAK	6-HOUR	24-HOUR	72-HOUR
1889.	718.	543.	543.
	8.78	8.86	8.86
	356.	359.	359.
			43462.
			8.86
			359.

CFS  
INCHES  
AC-FT



1801 SOUTH NAVAJO DENVER COLORADO 80231



# RUNOFF SUMMARY: AVERAGE FLOW

HYDROGRAPH AT ROUTED TO	PEAK	6-HOUR	24-HOUR	72-HOUR	AREA
3	1913.	723.	543.	543.	0.76
5	1889.	718.	543.	543.	0.76

TEOT

1911 SOUTH MAIN DENVER COLORADO 80202

\*\*\*\*\*  
HLC-1 VERSION DATED JAN 1973  
\*\*\*\*\*

DAM SAFETY INSPECTION - NEW JERSEY STATE  
HIGHLAND LAKE DAM  
PERCENT OF PWF FLOOD ROUTING

JOB SPECIFICATION  
NQ NHR NMN IDAY IHR IMIN METRC IPLT IPRT NSTAN  
80 0 6 0 0 0 0 0 0 0  
JUPEN NMT  
3 0

\*\*\*\*\*

SUB-AREA MUNDUFF COMPUTATION

INPUT UNIT HYDROGRAPH DERIVED FROM SCS METHOD

ISTAQ ICOMP IECUN IIAPE JPLT JPRT INAME  
5 0 0 0 0 0 1  
IHTOG IUNG TAREA SNAP TRSDA TRSPL RATIO ISNOW ISAME LOCAL  
0 -1 0.76 0.00 0.76 0.00 0.360 0 0 0

HYDROGRAPH DATA

NP	STORM	UAG	DAK
60	0.00	0.00	0.00
PRECIP PATTERN			
0.00	0.00	0.06	0.11
0.10	0.10	0.20	0.21
0.20	0.20	0.28	0.29
0.30	0.30	0.36	0.39
0.40	0.40	0.44	0.49
0.50	0.50	0.52	0.59
0.60	0.60	0.60	0.69
0.70	0.70	0.68	0.79
0.80	0.80	0.66	0.89
0.90	0.90	0.64	0.99
1.00	1.00	0.62	1.00

LOSS DATA

STMR	ULTR	RTIOL	ERAIN	STRKS	RTIOL	STRTL	CNSTL	ALSHX	RTIMP
0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00

0. 625. 1752. 1250. 625. 325. 150. 75. 30. 5.  
UNIT GRAPH TOTALS 4837. CFS ON 0.96 INCHES OVER THE AREA

RECESSION DATA  
STRTO= 0.00 ORCEN= 0.00 RTION= 1.00

END-OF-PERIOD FLOW

TIME	RAIN	EXCS	COMP
1	0.00	0.00	0.00
2	0.00	0.00	0.00
3	0.00	0.00	0.00
4	0.00	0.00	0.00



5	0.08	0.08	57.
6	0.11	0.11	155.
7	0.11	0.11	283.
8	0.13	0.13	398.
9	0.13	0.13	480.
10	0.15	0.15	550.
11	0.15	0.15	605.
12	0.18	0.18	679.
13	0.20	0.20	766.
14	0.20	0.20	852.
15	0.20	0.20	894.
16	0.21	0.21	933.
17	0.21	0.21	957.
18	0.21	0.21	984.
19	0.21	0.21	1001.
20	0.22	0.22	1009.
21	0.28	0.28	1019.
22	0.27	0.27	1075.
23	0.28	0.28	1188.
24	0.28	0.28	1258.
25	0.28	0.28	1304.
26	0.29	0.29	1351.
27	0.29	0.29	1350.
28	0.29	0.29	1374.
29	0.29	0.29	1369.
30	0.29	0.29	1396.
31	0.74	0.74	1400.
32	0.74	0.74	1682.
33	0.74	0.74	2472.
34	0.74	0.74	3054.
35	0.74	0.74	3216.
36	0.89	0.89	3462.
37	0.74	0.74	3623.
38	0.74	0.74	3626.
39	0.74	0.74	3764.
40	0.74	0.74	3673.
41	0.27	0.27	3628.
42	0.27	0.27	3308.
43	0.27	0.27	2473.
44	0.27	0.27	1679.
45	0.27	0.27	1581.
46	0.27	0.27	1428.
47	0.27	0.27	1357.
48	0.27	0.27	1322.
49	0.27	0.27	1308.
50	0.27	0.27	1305.
51	0.21	0.21	1305.
52	0.21	0.21	1268.
53	0.21	0.21	1163.
54	0.21	0.21	1088.
55	0.21	0.21	1050.
56	0.21	0.21	1031.
57	0.21	0.21	1022.
58	0.21	0.21	1017.
59	0.21	0.21	1016.
60	0.21	0.21	1015.
61	0.00	0.00	1015.
62	0.00	0.00	888.
63	0.00	0.00	518.
64	0.00	0.00	254.
65	0.00	0.00	123.

1901 SOUTH NAVAL, DENVER, COLORADO 80223

66	0.00	0.00	0.00	54.
67	0.00	0.00	0.00	23.
68	0.00	0.00	0.00	7.
69	0.00	0.00	0.00	1.
70	0.00	0.00	0.00	0.
71	0.00	0.00	0.00	0.
72	0.00	0.00	0.00	0.
73	0.00	0.00	0.00	0.
74	0.00	0.00	0.00	0.
75	0.00	0.00	0.00	0.
76	0.00	0.00	0.00	0.
77	0.00	0.00	0.00	0.
78	0.00	0.00	0.00	0.
79	0.00	0.00	0.00	0.
80	0.00	0.00	0.00	0.

SUM 17.98 17.98 86965.

CFS	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
INCHES	3826.	1447.	1087.	1087.	86969.
AC-FT		17.71	17.74	17.74	17.74
		718.	719.	719.	719.

RUNOFF MULTIPLIED BY 0.36

0.	0.	15.	55.	192.	143.	198.
217.	275.	322.	435.	344.	354.	363.
366.	427.	469.	479.	406.	494.	502.
504.	809.	1193.	1246.	1304.	1377.	1322.
1306.	890.	676.	569.	514.	488.	476.
470.	418.	378.	371.	368.	366.	365.
365.	185.	44.	19.	8.	2.	0.
0.	0.	0.	0.	0.	0.	0.

CFS	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
INCHES	1377.	521.	391.	391.	31308.
AC-FT		6.37	6.38	6.38	6.38
		258.	258.	258.	258.

# HYDROGRAPH ROUTING ROUTE HYDROGRAPH THROUGH HIGHLAND LAKE DAM

ISTAQ	ICOMP	IECUN	ITAPE	JPLT	JPR1	INAME
5	1	0	0	0	0	1

GLOSS	CLOSS	AVG	INES	184ML
0.0	0.000	0.00	1	0

NSIPS	NSIDL	LAG	APSKM	X	TSK	STORA
0	0	0	0.000	0.000	-1.	-1.

STORAGE	89.	52.	60.	52.	68.	56.	71.	77.
OUTFLOW	0.	100.	400.	840.	1160.	1400.	1770.	2100.
							2660.	4008.

TIME EOP S10R 1 49.0  
TIME EOP OUT 0.





3	49.	0.	0.
4	49.	0.	0.
5	49.	1.	0.
6	49.	6.	1.
7	49.	34.	7.
8	50.	79.	21.
9	51.	122.	41.
10	52.	158.	84.
11	53.	185.	88.
12	53.	207.	130.
13	54.	231.	180.
14	54.	260.	220.
15	55.	287.	254.
16	55.	310.	282.
17	55.	329.	305.
18	55.	340.	323.
19	55.	349.	336.
20	55.	357.	347.
21	56.	361.	354.
22	56.	365.	359.
23	56.	377.	368.
24	56.	407.	388.
25	56.	440.	418.
26	57.	461.	445.
27	57.	474.	463.
28	57.	482.	475.
29	57.	490.	485.
30	57.	497.	493.
31	57.	501.	498.
32	57.	503.	501.
33	58.	554.	535.
34	60.	747.	670.
35	62.	991.	876.
36	63.	1143.	1057.
37	63.	1220.	1176.
38	63.	1275.	1252.
39	64.	1341.	1320.
40	64.	1366.	1355.
41	63.	1388.	1342.
42	63.	1314.	1320.
43	62.	1248.	1265.
44	60.	1040.	1094.
45	59.	783.	883.
46	58.	622.	715.
47	57.	541.	604.
48	57.	501.	539.
49	57.	482.	503.
50	57.	473.	484.
51	57.	470.	475.
52	57.	470.	472.
53	56.	463.	466.
54	56.	457.	448.
55	56.	405.	420.
56	56.	385.	398.
57	56.	374.	386.
58	56.	369.	378.
59	56.	367.	372.
60	56.	366.	369.
61	56.	365.	367.
62	55.	388.	366.
		342.	384.





63	55	252	303
64	54	138	228
65	53	67	143
66	52	31	95
67	52	13	79
68	51	5	64
69	50	1	52
70	50	1	42
71	50	0	33
72	50	0	27
73	49	0	21
74	49	0	17
75	49	0	14
76	49	0	11
77	49	0	9
78	49	0	7
79	49	0	5
80	49	0	4
SUM			31289
PEAK	6-HOUR	24-HOUR	72-HOUR
1355	516	391	391
CFS	6.31	6.38	6.38
INCHES	256	258	258
AC-FT			

.....

TEOTI

1001 SOUTH NAVajo DENVER COLORADO 80202

RUNOFF SUMMARY, AVERAGE FLOW

HYDROGRAPH AT ROUTED TO	PEAK	AVERAGE FLOW			AREA
		6-HOUR	24-HOUR	72-HOUR	
5	1377.	541.	391.	391.	0.76
5	1355.	516.	391.	391.	0.76

TECOTL

1901 SOUTH MAIN AVE DENVER COLORADO 80202

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER NJ00240	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Phase I Inspection Report National Dam Safety Program Highland Lake Dam Passaic County, N.J.		5. TYPE OF REPORT & PERIOD COVERED (9) FINAL rept.
7. AUTHOR(s) (10) Robert Gershowitz, P.E.		6. PERFORMING ORG. REPORT NUMBER
9. PERFORMING ORGANIZATION NAME AND ADDRESS Harris-ECI Associates 453 Amboy Ave. Woodbridge, N.J. 07095		8. CONTRACT OR GRANT NUMBER(s) (15) DACW61-78-C-0124
11. CONTROLLING OFFICE NAME AND ADDRESS U.S. Army Engineer District, Philadelphia Custom House, 2d & Chestnut Streets Philadelphia, Pennsylvania 19106		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBER (12) 107p
14. <i>ing Office)</i> (6) National Dam Safety Program. Highland Lake Dam (NJ00240), Passaic River Basin, Slippery Rock Brook, Passaic County, New Jersey. Phase I Inspection Report.		12. REPORT DATE August, 1978
		13. NUMBER OF PAGES
		15. SECURITY CLASS. (of this report) Unclassified
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES Copies are obtainable from National Technical Information Service, Springfield, Virginia, 22151.		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Dams--N.J. National Dam Safety Program Phase I Highland Lake Dam, N.J. Dam Inspection Dam Safety		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) This report cites results of a technical investigation as to the dam's adequacy. The inspection and evaluation of the dam is as prescribed by the National Dam Inspection Act, Public Law 92-367. The technical investigation includes visual inspection, review of available design and construction records, and preliminary structural and hydraulic and hydrologic calculations, as applicable. An assessment of the dam's general condition is included in the report.		